

# CERTIFICATE OF COMPLIANCE

**Certificate Number** E306515  
**Report Reference** E306515-20200101  
**Date** 2021-May-31

**Issued to:** Trina Solar Co.,Ltd  
No.2 Tian he Road Trina PV Industrial Park  
New District  
ChangzhouJiangsu 213031 CN

**This is to certify that representative samples of** PHOTOVOLTAIC MODULES AND PANELS WITH SYSTEM VOLTAGE RATINGS OVER 600 VOLTS  
See Addendum Page for Product Designation(s).

Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.


**Standard(s) for Safety:** UL 61730-1 - Standard for Safety for Photovoltaic (PV) Module Safety Qualification - Part 1: Requirements for Construction  
UL 61730-2 - Standard for Safety for Photovoltaic (PV) Module Safety Qualification - Part 2: Requirements for Testing  
CSA C22.2 No. 61730-1 - Photovoltaic (PV) module safety qualification — Part 1: Requirements for construction  
CSA C22.2 No. 61730-2 - Photovoltaic (PV) module safety qualification — Part 2: Requirements for testing

**Additional Information:** See the UL Online Certifications Directory at <https://iq.ulprospector.com> for additional information

This Certificate of Compliance does not provide authorization to apply the UL Mark. Only the UL Follow-Up Services Procedure provides authorization to apply the UL Mark.

Only those products bearing the UL Mark should be considered as being UL Certified and covered under UL's Follow-Up Services.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** E306515  
**Report Reference** E306515-20200101  
**Date** 2021-May-31

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements

Product Designation:

USL/CNL - Photovoltaic Module, Models:

TSM-280PD06H, TSM-285PD06H, TSM-290PD06H, TSM-295PD06H, TSM-300PD06H, TSM-305PD06H, TSM-310PD06H, TSM-315PD06H, TSM-320PD06H;

TSM-280PD06H.08, TSM-285PD06H.08, TSM-290PD06H.08, TSM-295PD06H.08, TSM-300PD06H.08, TSM-305PD06H.08, TSM-310PD06H.08, TSM-315PD06H.08, TSM-320PD06H.08;

TSM-280PD06H.T0, TSM-285PD06H.T0, TSM-290PD06H.T0, TSM-295PD06H.T0, TSM-300PD06H.T0, TSM-305PD06H.T0, TSM-310PD06H.T0, TSM-315PD06H.T0, TSM-320PD06H.T0;

TSM-280PD06H.T8, TSM-285PD06H.T8, TSM-290PD06H.T8, TSM-295PD06H.T8, TSM-300PD06H.T8, TSM-305PD06H.T8, TSM-310PD06H.T8, TSM-315PD06H.T8, TSM-320PD06H.T8;  
TSM-335PD15H, TSM-340PD15H, TSM-345PD15H, TSM-350PD15H, TSM-355PD15H, TSM-360PD15H, TSM-365PD15H, TSM-370PD15H, TSM-375PD15H, TSM-380PD15H, TSM-385PD15H;

TSM-335PD15H.08, TSM-340PD15H.08, TSM-345PD15H.08, TSM-350PD15H.08, TSM-355PD15H.08, TSM-360PD15H.08, TSM-365PD15H.08, TSM-370PD15H.08, TSM-375PD15H.08, TSM-380PD15H.08, TSM-385PD15H.08;

TSM-335PD15H.T0, TSM-340PD15H.T0, TSM-345PD15H.T0, TSM-350PD15H.T0, TSM-355PD15H.T0, TSM-360PD15H.T0, TSM-365PD15H.T0, TSM-370PD15H.T0, TSM-375PD15H.T0, TSM-380PD15H.T0, TSM-385PD15H.T0;


TSM-335PD15H.T8, TSM-340PD15H.T8, TSM-345PD15H.T8, TSM-350PD15H.T8, TSM-355PD15H.T8, TSM-360PD15H.T8, TSM-365PD15H.T8, TSM-370PD15H.T8, TSM-375PD15H.T8, TSM-380PD15H.T8, TSM-385PD15H.T8;

TSM-315DD06H(II), TSM-320DD06H(II), TSM-325DD06H(II), TSM-330DD06H(II), TSM-335DD06H(II), TSM-340DD06H(II), TSM-345DD06H(II), TSM-350DD06H(II);

TSM-315DD06H.05(II), TSM-320DD06H.05(II), TSM-325DD06H.05(II), TSM-330DD06H.05(II), TSM-335DD06H.05(II), TSM-340DD06H.05(II), TSM-345DD06H.05(II), TSM-350DD06H.05(II);

TSM-315DD06H.08(II), TSM-320DD06H.08(II), TSM-325DD06H.08(II), TSM-330DD06H.08(II), TSM-335DD06H.08(II), TSM-340DD06H.08(II), TSM-345DD06H.08(II), TSM-350DD06H.08(II);

TSM-315DD06H.T0(II), TSM-320DD06H.T0(II), TSM-325DD06H.T0(II), TSM-330DD06H.T0(II), TSM-335DD06H.T0(II), TSM-340DD06H.T0(II), TSM-345DD06H.T0(II), TSM-350DD06H.T0(II);



Bruce Mahrenholz, Director North American Certification Program

UL LLC



# CERTIFICATE OF COMPLIANCE

**Certificate Number** E306515  
**Report Reference** E306515-20200101  
**Date** 2021-May-31

TSM-315DD06H.T8(II), TSM-320DD06H.T8(II), TSM-325DD06H.T8(II), TSM-330DD06H.T8(II),  
TSM-335DD06H.T8(II), TSM-340DD06H.T8(II), TSM-345DD06H.T8(II), TSM-350DD06H.T8(II);

TSM-380DD15H(II), TSM-385DD15H(II), TSM-390DD15H(II), TSM-395DD15H(II), TSM-  
400DD15H(II), TSM-405DD15H(II), TSM-410DD15H(II), TSM-415DD15H(II), TSM-420DD15H(II);

TSM-380DD15H.05(II), TSM-385DD15H.05(II), TSM-390DD15H.05(II), TSM-395DD15H.05(II), TSM-  
400DD15H.05(II), TSM-405DD15H.05(II), TSM-410DD15H.05(II), TSM-415DD15H.05(II), TSM-  
420DD15H.05(II);

TSM-380DD15H.08(II), TSM-385DD15H.08(II), TSM-390DD15H.08(II), TSM-395DD15H.08(II), TSM-  
400DD15H.08(II), TSM-405DD15H.08(II), TSM-410DD15H.08(II), TSM-415DD15H.08(II), TSM-  
420DD15H.08(II);

TSM-380DD15H.T0(II), TSM-385DD15H.T0(II), TSM-390DD15H.T0(II), TSM-395DD15H.T0(II),  
TSM-400DD15H.T0(II), TSM-405DD15H.T0(II), TSM-410DD15H.T0(II), TSM-415DD15H.T0(II),  
TSM-420DD15H.T0(II);

TSM-380DD15H.T8(II), TSM-385DD15H.T8(II), TSM-390DD15H.T8(II), TSM-395DD15H.T8(II),  
TSM-400DD15H.T8(II), TSM-405DD15H.T8(II), TSM-410DD15H.T8(II), TSM-415DD15H.T8(II),  
TSM-420DD15H.T8(II);

TSM-315DD06M(II), TSM-320DD06M(II), TSM-325DD06M(II), TSM-330DD06M(II), TSM-  
335DD06M(II), TSM-340DD06M(II), TSM-345DD06M(II), TSM-350DD06M(II);

TSM-315DD06M.05(II), TSM-320DD06M.05(II), TSM-325DD06M.05(II), TSM-330DD06M.05(II),  
TSM-335DD06M.05(II), TSM-340DD06M.05(II), TSM-345DD06M.05(II), TSM-350DD06M.05(II);

TSM-315DD06M.08(II), TSM-320DD06M.08(II), TSM-325DD06M.08(II), TSM-330DD06M.08(II),  
TSM-335DD06M.08(II), TSM-340DD06M.08(II), TSM-345DD06M.08(II), TSM-350DD06M.08(II);


TSM-315DD06M.T0(II), TSM-320DD06M.T0(II), TSM-325DD06M.T0(II), TSM-330DD06M.T0(II),  
TSM-335DD06M.T0(II), TSM-340DD06M.T0(II), TSM-345DD06M.T0(II), TSM-350DD06M.T0(II);

TSM-315DD06M.T8(II), TSM-320DD06M.T8(II), TSM-325DD06M.T8(II), TSM-330DD06M.T8(II),  
TSM-335DD06M.T8(II), TSM-340DD06M.T8(II), TSM-345DD06M.T8(II), TSM-350DD06M.T8(II);

TSM-380DD15M(II), TSM-385DD15M(II), TSM-390DD15M(II), TSM-395DD15M(II), TSM-  
400DD15M(II), TSM-405DD15M(II), TSM-410DD15M(II), TSM-415DD15M(II), TSM-420DD15M(II);

TSM-380DD15M.05(II), TSM-385DD15M.05(II), TSM-390DD15M.05(II), TSM-395DD15M.05(II),  
TSM-400DD15M.05(II), TSM-405DD15M.05(II), TSM-410DD15M.05(II), TSM-415DD15M.05(II),  
TSM-420DD15M.05(II);

TSM-380DD15M.08(II), TSM-385DD15M.08(II), TSM-390DD15M.08(II), TSM-395DD15M.08(II),  
TSM-400DD15M.08(II), TSM-405DD15M.08(II), TSM-410DD15M.08(II), TSM-415DD15M.08(II),  
TSM-420DD15M.08(II);



Bruce Mahrenholz, Director North American Certification Program

UL LLC



Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** E306515  
**Report Reference** E306515-20200101  
**Date** 2021-May-31

TSM-380DD15M.T0(II), TSM-385DD15M.T0(II), TSM-390DD15M.T0(II), TSM-395DD15M.T0(II),  
TSM-400DD15M.T0(II), TSM-405DD15M.T0(II), TSM-410DD15M.T0(II), TSM-415DD15M.T0(II),  
TSM-420DD15M.T0(II);

TSM-380DD15M.T8(II), TSM-385DD15M.T8(II), TSM-390DD15M.T8(II), TSM-395DD15M.T8(II),  
TSM-400DD15M.T8(II), TSM-405DD15M.T8(II), TSM-410DD15M.T8(II), TSM-415DD15M.T8(II),  
TSM-420DD15M.T8(II);

TSM-280PE06H, TSM-285PE06H, TSM-290PE06H, TSM-295PE06H, TSM-300PE06H, TSM-  
305PE06H, TSM-310PE06H, TSM-315PE06H, TSM-320PE06H;

TSM-280PE06H.08, TSM-285PE06H.08, TSM-290PE06H.08, TSM-295PE06H.08, TSM-  
300PE06H.08, TSM-305PE06H.08, TSM-310PE06H.08, TSM-315PE06H.08, TSM-320PE06H.08;

TSM-280PE06H.T0, TSM-285PE06H.T0, TSM-290PE06H.T0, TSM-295PE06H.T0, TSM-  
300PE06H.T0, TSM-305PE06H.T0, TSM-310PE06H.T0, TSM-315PE06H.T0, TSM-320PE06H.T0;

TSM-280PE06H.T8, TSM-285PE06H.T8, TSM-290PE06H.T8, TSM-295PE06H.T8, TSM-  
300PE06H.T8, TSM-305PE06H.T8, TSM-310PE06H.T8, TSM-315PE06H.T8, TSM-320PE06H.T8;

TSM-335PE15H, TSM-340PE15H, TSM-345PE15H, TSM-350PE15H, TSM-355PE15H, TSM-  
360PE15H, TSM-365PE15H, TSM-370PE15H, TSM-375PE15H, TSM-380PE15H, TSM-385PE15H;

TSM-335PE15H.08, TSM-340PE15H.08, TSM-345PE15H.08, TSM-350PE15H.08, TSM-  
355PE15H.08, TSM-360PE15H.08, TSM-365PE15H.08, TSM-370PE15H.08, TSM-375PE15H.08,  
TSM-380PE15H.08, TSM-385PE15H.08;

TSM-335PE15H.T0, TSM-340PE15H.T0, TSM-345PE15H.T0, TSM-350PE15H.T0, TSM-  
355PE15H.T0, TSM-360PE15H.T0, TSM-365PE15H.T0, TSM-370PE15H.T0, TSM-375PE15H.T0,  
TSM-380PE15H.T0, TSM-385PE15H.T0;


TSM-335PE15H.T8, TSM-340PE15H.T8, TSM-345PE15H.T8, TSM-350PE15H.T8, TSM-  
355PE15H.T8, TSM-360PE15H.T8, TSM-365PE15H.T8, TSM-370PE15H.T8, TSM-375PE15H.T8,  
TSM-380PE15H.T8, TSM-385PE15H.T8;

TSM-315DE06H(II), TSM-320DE06H(II), TSM-325DE06H(II), TSM-330DE06H(II), TSM-  
335DE06H(II), TSM-340DE06H(II), TSM-345DE06H(II), TSM-350DE06H(II);

TSM-315DE06H.05(II), TSM-320DE06H.05(II), TSM-325DE06H.05(II), TSM-330DE06H.05(II), TSM-  
335DE06H.05(II), TSM-340DE06H.05(II), TSM-345DE06H.05(II), TSM-350DE06H.05(II);

TSM-315DE06H.08(II), TSM-320DE06H.08(II), TSM-325DE06H.08(II), TSM-330DE06H.08(II), TSM-  
335DE06H.08(II), TSM-340DE06H.08(II), TSM-345DE06H.08(II), TSM-350DE06H.08(II);

TSM-315DE06H.T0(II), TSM-320DE06H.T0(II), TSM-325DE06H.T0(II), TSM-330DE06H.T0(II), TSM-  
335DE06H.T0(II), TSM-340DE06H.T0(II), TSM-345DE06H.T0(II), TSM-350DE06H.T0(II);



Bruce Mahrenholz, Director North American Certification Program



UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations>

# CERTIFICATE OF COMPLIANCE

**Certificate Number** E306515  
**Report Reference** E306515-20200101  
**Date** 2021-May-31

TSM-315DE06H.T8(II), TSM-320DE06H.T8(II), TSM-325DE06H.T8(II), TSM-330DE06H.T8(II), TSM-335DE06H.T8(II), TSM-340DE06H.T8(II), TSM-345DE06H.T8(II), TSM-350DE06H.T8(II);

TSM-380DE15H(II), TSM-385DE15H(II), TSM-390DE15H(II), TSM-395DE15H(II), TSM-400DE15H(II), TSM-405DE15H(II), TSM-410DE15H(II), TSM-415DE15H(II), TSM-420DE15H(II);

TSM-380DE15H.05(II), TSM-385DE15H.05(II), TSM-390DE15H.05(II), TSM-395DE15H.05(II), TSM-400DE15H.05(II), TSM-405DE15H.05(II), TSM-410DE15H.05(II), TSM-415DE15H.05(II), TSM-420DE15H.05(II);

TSM-380DE15H.08(II), TSM-385DE15H.08(II), TSM-390DE15H.08(II), TSM-395DE15H.08(II), TSM-400DE15H.08(II), TSM-405DE15H.08(II), TSM-410DE15H.08(II), TSM-415DE15H.08(II), TSM-420DE15H.08(II);

TSM-380DE15H.T0(II), TSM-385DE15H.T0(II), TSM-390DE15H.T0(II), TSM-395DE15H.T0(II), TSM-400DE15H.T0(II), TSM-405DE15H.T0(II), TSM-410DE15H.T0(II), TSM-415DE15H.T0(II), TSM-420DE15H.T0(II);

TSM-380DE15H.T8(II), TSM-385DE15H.T8(II), TSM-390DE15H.T8(II), TSM-395DE15H.T8(II), TSM-400DE15H.T8(II), TSM-405DE15H.T8(II), TSM-410DE15H.T8(II), TSM-415DE15H.T8(II), TSM-420DE15H.T8(II);

TSM-315DE06M(II), TSM-320DE06M(II), TSM-325DE06M(II), TSM-330DE06M(II), TSM-335DE06M(II), TSM-340DE06M(II), TSM-345DE06M(II), TSM-350DE06M(II);

TSM-315DE06M.05(II), TSM-320DE06M.05(II), TSM-325DE06M.05(II), TSM-330DE06M.05(II), TSM-335DE06M.05(II), TSM-340DE06M.05(II), TSM-345DE06M.05(II), TSM-350DE06M.05(II);

TSM-315DE06M.08(II), TSM-320DE06M.08(II), TSM-325DE06M.08(II), TSM-330DE06M.08(II), TSM-335DE06M.08(II), TSM-340DE06M.08(II), TSM-345DE06M.08(II), TSM-350DE06M.08(II);


TSM-315DE06M.T0(II), TSM-320DE06M.T0(II), TSM-325DE06M.T0(II), TSM-330DE06M.T0(II), TSM-335DE06M.T0(II), TSM-340DE06M.T0(II), TSM-345DE06M.T0(II), TSM-350DE06M.T0(II);

TSM-315DE06M.T8(II), TSM-320DE06M.T8(II), TSM-325DE06M.T8(II), TSM-330DE06M.T8(II), TSM-335DE06M.T8(II), TSM-340DE06M.T8(II), TSM-345DE06M.T8(II), TSM-350DE06M.T8(II);

TSM-380DE15M(II), TSM-385DE15M(II), TSM-390DE15M(II), TSM-395DE15M(II), TSM-400DE15M(II), TSM-405DE15M(II), TSM-410DE15M(II), TSM-415DE15M(II), TSM-420DE15M(II);

TSM-380DE15M.05(II), TSM-385DE15M.05(II), TSM-390DE15M.05(II), TSM-395DE15M.05(II), TSM-400DE15M.05(II), TSM-405DE15M.05(II), TSM-410DE15M.05(II), TSM-415DE15M.05(II), TSM-420DE15M.05(II);

TSM-380DE15M.08(II), TSM-385DE15M.08(II), TSM-390DE15M.08(II), TSM-395DE15M.08(II), TSM-400DE15M.08(II), TSM-405DE15M.08(II), TSM-410DE15M.08(II), TSM-415DE15M.08(II), TSM-420DE15M.08(II);



Bruce Mahrenholz, Director North American Certification Program

UL LLC





# CERTIFICATE OF COMPLIANCE

**Certificate Number** E306515  
**Report Reference** E306515-20200101  
**Date** 2021-May-31

TSM-380DE15M.T0(II), TSM-385DE15M.T0(II), TSM-390DE15M.T0(II), TSM-395DE15M.T0(II),  
TSM-400DE15M.T0(II), TSM-405DE15M.T0(II), TSM-410DE15M.T0(II), TSM-415DE15M.T0(II),  
TSM-420DE15M.T0(II);

TSM-380DE15M.T8(II), TSM-385DE15M.T8(II), TSM-390DE15M.T8(II), TSM-395DE15M.T8(II),  
TSM-400DE15M.T8(II), TSM-405DE15M.T8(II), TSM-410DE15M.T8(II), TSM-415DE15M.T8(II),  
TSM-420DE15M.T8(II);

TSM-330DD171H(II), TSM-335DD171H(II), TSM-340DD171H(II), TSM-345DD171H(II), TSM-  
350DD171H(II);

TSM-330DD171H.05(II), TSM-335DD171H.05(II), TSM-340DD171H.05(II), TSM-345DD171H.05(II),  
TSM-350DD171H.05(II);

TSM-330DD171H.08(II), TSM-335DD171H.08(II), TSM-340DD171H.08(II), TSM-345DD171H.08(II),  
TSM-350DD171H.08(II);

TSM-330DD171H.T0(II), TSM-335DD171H.T0(II), TSM-340DD171H.T0(II), TSM-345DD171H.T0(II),  
TSM-350DD171H.T0(II);

TSM-330DD171H.T8(II), TSM-335DD171H.T8(II), TSM-340DD171H.T8(II), TSM-345DD171H.T8(II),  
TSM-350DD171H.T8(II);

TSM-330DE171H(II), TSM-335DE171H(II), TSM-340DE171H(II), TSM-345DE171H(II), TSM-  
350DE171H(II);

TSM-330DE171H.05(II), TSM-335DE171H.05(II), TSM-340DE171H.05(II), TSM-345DE171H.05(II),  
TSM-350DE171H.05(II);

TSM-330DE171H.08(II), TSM-335DE171H.08(II), TSM-340DE171H.08(II), TSM-345DE171H.08(II),  
TSM-350DE171H.08(II);


TSM-330DE171H.T0(II), TSM-335DE171H.T0(II), TSM-340DE171H.T0(II), TSM-345DE171H.T0(II),  
TSM-350DE171H.T0(II);

TSM-330DE171H.T8(II), TSM-335DE171H.T8(II), TSM-340DE171H.T8(II), TSM-345DE171H.T8(II),  
TSM-350DE171H.T8(II);

TSM-480DD18M(II), TSM-485DD18M(II), TSM-490DD18M(II), TSM-495DD18M(II), TSM-  
500DD18M(II), TSM-505DD18M(II), TSM-510DD18M(II);

TSM-480DD18M.05(II), TSM-485DD18M.05(II), TSM-490DD18M.05(II), TSM-495DD18M.05(II),  
TSM-500DD18M.05(II), TSM-505DD18M.05(II), TSM-510DD18M.05(II);

TSM-480DD18M.08(II), TSM-485DD18M.08(II), TSM-490DD18M.08(II), TSM-495DD18M.08(II),  
TSM-500DD18M.08(II), TSM-505DD18M.08(II), TSM-510DD18M.08(II);



Bruce Mahrenholz, Director North American Certification Program

UL LLC



# CERTIFICATE OF COMPLIANCE

**Certificate Number** E306515  
**Report Reference** E306515-20200101  
**Date** 2021-May-31

TSM-480DD18M.T0(II), TSM-485DD18M.T0(II), TSM-490DD18M.T0(II), TSM-495DD18M.T0(II),  
TSM-500DD18M.T0(II), TSM-505DD18M.T0(II), TSM-510DD18M.T0(II);

TSM-480DD18M.T8(II), TSM-485DD18M.T8(II), TSM-490DD18M.T8(II), TSM-495DD18M.T8(II),  
TSM-500DD18M.T8(II), TSM-505DD18M.T8(II), TSM-510DD18M.T8(II);

TSM-480DE18M(II), TSM-485DE18M(II), TSM-490DE18M(II), TSM-495DE18M(II), TSM-  
500DE18M(II), TSM-505DE18M(II), TSM-510DE18M(II);

TSM-480DE18M.05(II), TSM-485DE18M.05(II), TSM-490DE18M.05(II), TSM-495DE18M.05(II),  
TSM-500DE18M.05(II), TSM-505DE18M.05(II), TSM-510DE18M.05(II);

TSM-480DE18M.08(II), TSM-485DE18M.08(II), TSM-490DE18M.08(II), TSM-495DE18M.08(II),  
TSM-500DE18M.08(II), TSM-505DE18M.08(II), TSM-510DE18M.08(II);

TSM-480DE18M.T0(II), TSM-485DE18M.T0(II), TSM-490DE18M.T0(II), TSM-495DE18M.T0(II),  
TSM-500DE18M.T0(II), TSM-505DE18M.T0(II), TSM-510DE18M.T0(II);

TSM-480DE18M.T8(II), TSM-485DE18M.T8(II), TSM-490DE18M.T8(II), TSM-495DE18M.T8(II),  
TSM-500DE18M.T8(II), TSM-505DE18M.T8(II), TSM-510DE18M.T8(II);

TSM-530DD19, TSM-535DD19, TSM-540DD19, TSM-545DD19, TSM-550DD19;

TSM-530DD19.05, TSM-535DD19.05, TSM-540DD19.05, TSM-545DD19.05, TSM-550DD19.05;

TSM-530DD19.08, TSM-535DD19.08, TSM-540DD19.08, TSM-545DD19.08, TSM-550DD19.08;

TSM-530DD19.T0, TSM-535DD19.T0, TSM-540DD19.T0, TSM-545DD19.T0, TSM-550DD19.T0;

TSM-530DD19.T8, TSM-535DD19.T8, TSM-540DD19.T8, TSM-545DD19.T8, TSM-550DD19.T8;

TSM-530DE19, TSM-535DE19, TSM-540DE19, TSM-545DE19, TSM-550DE19;

TSM-530DE19.05, TSM-535DE19.05, TSM-540DE19.05, TSM-545DE19.05, TSM-550DE19.05;


TSM-530DE19.08, TSM-535DE19.08, TSM-540DE19.08, TSM-545DE19.08, TSM-550DE19.08;

TSM-530DE19.T0, TSM-535DE19.T0, TSM-540DE19.T0, TSM-545DE19.T0, TSM-550DE19.T0;

TSM-530DE19.T8, TSM-535DE19.T8, TSM-540DE19.T8, TSM-545DE19.T8, TSM-550DE19.T8;

TSM-530DD19C, TSM-535DD19C, TSM-540DD19C, TSM-545DD19C, TSM-550DD19C;

TSM-530DD19C.08, TSM-535DD19C.08, TSM-540DD19C.08, TSM-545DD19C.08, TSM-  
550DD19C.08;



Bruce Mahrenholz, Director North American Certification Program

UL LLC




Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

# CERTIFICATE OF COMPLIANCE

**Certificate Number** E306515  
**Report Reference** E306515-20200101  
**Date** 2021-May-31

TSM-530DE19C, TSM-535DE19C, TSM-540DE19C, TSM-545DE19C, TSM-550DE19C;  
TSM-530DE19C.08, TSM-535DE19C.08, TSM-540DE19C.08, TSM-545DE19C.08, TSM-550DE19C.08;  
TSM-580DD20, TSM-585DD20, TSM-590DD20, TSM-595DD20, TSM-600DD20;  
TSM-580DD20.05, TSM-585DD20.05, TSM-590DD20.05, TSM-595DD20.05, TSM-600DD20.05;  
TSM-580DD20.08, TSM-585DD20.08, TSM-590DD20.08, TSM-595DD20.08, TSM-600DD20.08;  
TSM-580DD20.T0, TSM-585DD20.T0, TSM-590DD20.T0, TSM-595DD20.T0, TSM-600DD20.T0;  
TSM-580DD20.T8, TSM-585DD20.T8, TSM-590DD20.T8, TSM-595DD20.T8, TSM-600DD20.T8;  
TSM-580DE20, TSM-585DE20, TSM-590DE20, TSM-595DE20, TSM-600DE20;  
TSM-580DE20.05, TSM-585DE20.05, TSM-590DE20.05, TSM-595DE20.05, TSM-600DE20.05;  
TSM-580DE20.08, TSM-585DE20.08, TSM-590DE20.08, TSM-595DE20.08, TSM-600DE20.08;  
TSM-580DE20.T0, TSM-585DE20.T0, TSM-590DE20.T0, TSM-595DE20.T0, TSM-600DE20.T0;  
TSM-580DE20.T8, TSM-585DE20.T8, TSM-590DE20.T8, TSM-595DE20.T8, TSM-600DE20.T8;  
TSM-580DD20C, TSM-585DD20C, TSM-590DD20C, TSM-595DD20C, TSM-600DD20C;  
TSM-580DD20C.08, TSM-585DD20C.08, TSM-590DD20C.08, TSM-595DD20C.08, TSM-600DD20C.08;  
TSM-580DE20C, TSM-585DE20C, TSM-590DE20C, TSM-595DE20C, TSM-600DE20C;  
TSM-580DE20C.08, TSM-585DE20C.08, TSM-590DE20C.08, TSM-595DE20C.08, TSM-600DE20C.08;  
TSM-465DD15V(II), TSM-470DD15V(II), TSM-475DD15V(II), TSM-480DD15V(II), TSM-485DD15V(II), TSM-490DD15V(II);  
TSM-465DD15V.05(II), TSM-470DD15V.05(II), TSM-475DD15V.05(II), TSM-480DD15V.05(II), TSM-485DD15V.05(II), TSM-490DD15V.05(II);  
TSM-465DD15V.08(II), TSM-470DD15V.08(II), TSM-475DD15V.08(II), TSM-480DD15V.08(II), TSM-485DD15V.08(II), TSM-490DD15V.08(II);  
TSM-465DD15V.T0(II), TSM-470DD15V.T0(II), TSM-475DD15V.T0(II), TSM-480DD15V.T0(II), TSM-485DD15V.T0(II), TSM-490DD15V.T0(II);



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations>





# CERTIFICATE OF COMPLIANCE

**Certificate Number** E306515  
**Report Reference** E306515-20200101  
**Date** 2021-May-31

TSM-465DD15V.T8(II), TSM-470DD15V.T8(II), TSM-475DD15V.T8(II), TSM-480DD15V.T8(II), TSM-485DD15V.T8(II), TSM-490DD15V.T8(II);

TSM-465DE15V(II), TSM-470DE15V(II), TSM-475DE15V(II), TSM-480DE15V(II), TSM-485DE15V(II), TSM-490DE15V(II);

TSM-465DE15V.05(II), TSM-470DE15V.05(II), TSM-475DE15V.05(II), TSM-480DE15V.05(II), TSM-485DE15V.05(II), TSM-490DE15V.05(II);

TSM-465DE15V.08(II), TSM-470DE15V.08(II), TSM-475DE15V.08(II), TSM-480DE15V.08(II), TSM-485DE15V.08(II), TSM-490DE15V.08(II);

TSM-465DE15V.T0(II), TSM-470DE15V.T0(II), TSM-475DE15V.T0(II), TSM-480DE15V.T0(II), TSM-485DE15V.T0(II), TSM-490DE15V.T0(II);

TSM-465DE15V.T8(II), TSM-470DE15V.T8(II), TSM-475DE15V.T8(II), TSM-480DE15V.T8(II), TSM-485DE15V.T8(II), TSM-490DE15V.T8(II);

TSM-355DD06X(II), TSM-360DD06X(II), TSM-365DD06X(II), TSM-370DD06X(II), TSM-375DD06X(II), TSM-380DD06X(II);

TSM-355DD06X.05(II), TSM-360DD06X.05(II), TSM-365DD06X.05(II), TSM-370DD06X.05(II), TSM-375DD06X.05(II), TSM-380DD06X.05(II);

TSM-355DD06XC.08(II), TSM-360DD06XC.08(II), TSM-365DD06XC.08(II), TSM-370DD06XC.08(II), TSM-375DD06XC.08(II), TSM-380DD06XC.08(II);

TSM-355DE06X(II), TSM-360DE06X(II), TSM-365DE06X(II), TSM-370DE06X(II), TSM-375DE06X(II), TSM-380DE06X(II);

TSM-355DE06X.05(II), TSM-360DE06X.05(II), TSM-365DE06X.05(II), TSM-370DE06X.05(II), TSM-375DE06X.05(II), TSM-380DE06X.05(II);

TSM-355DE06XC.08(II), TSM-360DE06XC.08(II), TSM-365DE06XC.08(II), TSM-370DE06XC.08(II), TSM-375DE06XC.08(II), TSM-380DE06XC.08(II);

TSM-380DD09, TSM-385DD09, TSM-390DD09, TSM-395DD09, TSM-400DD09;


TSM-380DD09.05, TSM-385DD09.05, TSM-390DD09.05, TSM-395DD09.05, TSM-400DD09.05;

TSM-380DD09.08, TSM-385DD09.08, TSM-390DD09.08, TSM-395DD09.08, TSM-400DD09.08;

TSM-380DD09.T0, TSM-385DD09.T0, TSM-390DD09.T0, TSM-395DD09.T0, TSM-400DD09.T0;

TSM-380DD09.T8, TSM-385DD09.T8, TSM-390DD09.T8, TSM-395DD09.T8, TSM-400DD09.T8;

TSM-380DE09, TSM-385DE09, TSM-390DE09, TSM-395DE09, TSM-400DE09;



Bruce Mahrenholz, Director North American Certification Program

UL LLC


Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** E306515  
**Report Reference** E306515-20200101  
**Date** 2021-May-31

TSM-380DE09.05, TSM-385DE09.05, TSM-390DE09.05, TSM-395DE09.05, TSM-400DE09.05;  
TSM-380DE09.08, TSM-385DE09.08, TSM-390DE09.08, TSM-395DE09.08, TSM-400DE09.08;  
TSM-380DE09.T0, TSM-385DE09.T0, TSM-390DE09.T0, TSM-395DE09.T0, TSM-400DE09.T0;  
TSM-380DE09.T8, TSM-385DE09.T8, TSM-390DE09.T8, TSM-395DE09.T8, TSM-400DE09.T8;



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

