



Mobile APP Quick Guide



Download

1.1 Download through the app market

Android: Google Play search for "SRNE Monitoring"

iOS: App Store search for "SRNE Monitoring"

1.2 Scan the following QR code to download







2.1 Open APP



Once downloaded, turn on your Bluetooth and open the app



Connect

2.2 Adding Bluetooth device



Add Bluetooth device from search list



Connect

2.3 View device details



View real-time data, history data and basic information from your device



Setup

2.4 Setup Parameter Value

Purumeter Set (19 (4)	
attery settings	~
System voltage(V) Auto	Battery type Lead acid battery SLD
harger settings	~
Maximum charge(A) 0.05	CHG/CHG On Off
Upper limit of charge("C) 60.0	Lower limit of charge("C)
Overvoltage(V) 16.0	Limit charge voltage(V) 15.5
Boost charge voltage(V) 14.4	Floating charge voltage(V) 13.8
Boost charge return voltage(V) 13.2	Boost charge time(min) 120



View parameters

change parameter value and click "OK"



Other functions

3.1 Temperature Convert



Switch between $^\circ F$ and $^\circ C$



Other functions

3.2 Demo Library



View product information of SRNE



Other functions

3.3 User Feedback



Describe your feedback and we will serve you